1675 Pioneer Way, Suite C
El Cajon, CA 92020

Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

Affected Part Numbers:

- MRCB-24-N-(10A~50A)
- MRCB-24-H-(10A~50A)
- MRCB-24-V-(10A~50A)

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- MRCB-24-N series is replaced by MRCB-N series
- MRCB-24-H series is replaced by MRCB-H series
- MRCB-24-V series is replaced by MRCB-V series

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny
Position: Product Manager
Date Issued: 10/15/2026
Samuel Kenny

P: (619) 593 5050 **F:** (619) 593 5055 WWW.OPTIFUSE.COM