UL Product iQ®



Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at https://www.ul.com/about/locations.

Fuseholders, Cartridge Fuse - Component

COMPANY

OPTIFUSE

Suite C 1675 Pioneer Way El Cajon, CA 92020 United States

E520672

Marking: Company name and model designation.

Note: For additional marking information, refer to the <u>Guide Information Page</u>

View model for additional information

Model(s): BLC-20A, BLC-20C, LPA-21B, LPA-24B-12R, LPA-24B-14R, LPC-21W, LPC-24B-12R, PMA-DB-02-Q1S, PMA-DB-04-Q1S, PMA-DB-05-Q1R, PMA-DS-01-Q1S, PMA-DS-02-Q1S, PMA-DS-03-Q2S, PMA-DS-04-Q1S, PMA-DS-05-Q1R, PMA-DS-05-Q1R, PMA-DS-05-Q1R-SP, PMA-DS-06-SOS, PMA-DS-07-SOS, PMA-KB-01H-SOS, PMA-KB-01-SOS, PMA-KB-02-Q1S, PMA-KB-03-Q2S, PMA-KB-05-Q1R, PMA-KB-06-Q1S, PMA-KB-07-Q1R, PMA-KB-09-Q2S, PMA-KS-02-Q1S, PMA-KS-05-Q1R, PMA-KS-06-Q1S, PMC-DS-01-SOS, PMC-MS-01-Q2S, PMC-KB-01-Q2S, PMC-KB-01-Q2S, PMC-MS-01-Q2S, PMC-DS-01-Q2S, PMC-DS-

Last Updated on 2024-03-01

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2024 UL LLC."