

## Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

Affected Part Numbers:

MRCBP-24-N-(10A~50A)  
MRCBP-24-H-(10A~50A)  
MRCBP-24-V-(10A~50A)

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- MRCBP-24-N series is replaced by MRCBP-N series
- MRCBP-24-H series is replaced by MRCBP-H series
- MRCBP-24-V series is replaced by MRCBP-V series

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny  
Position: Product Manager  
Date Issued: 01/01/2024