

Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

Affected Part Numbers:

APS-(2A~30A)

APS-I-(2A~30A)

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- APS series parts are recommended to switch to ANS series
- APS-I series parts are recommended to switch to ANS-I series parts

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny

Position: Product Manager

Date Issued: 04/01/2024