

## Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

### Affected Part Numbers:

- R1206-005
- R1206-010
- R1206-012
- R1206-016
- R1206-020
- R1206-025
- R1206-035
- R1206-050

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- R1206-005 is replaced by R1206-005-R
- R1206-010 is replaced by R1206-010-R
- R1206-012 is replaced by R1206-012-R
- R1206-016 is replaced by R1206-016-R
- R1206-020 is replaced by R1206-020-R
- R1206-025 is replaced by R1206-025-R
- R1206-035 is replaced by R1206-035-R
- R1206-050 is replaced by R1206-050-R

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny

Position: Product Manager

Date Issued: April 29<sup>th</sup>, 2026

*Samuel Kenny*