

Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

Affected Part Numbers:

- R1210-005
- R1210-010
- R1210-020
- R1210-035
- R1210-050
- R1210-075

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- R1210-005 is replaced by R1210-005-R
- R1210-010 is replaced by R1210-010-R
- R1210-020 is replaced by R1210-020-R
- R1210-035 is replaced by R1210-035-R
- R1210-050 is replaced by R1210-050-R
- R1210-075 is replaced by R1210-075-R

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny

Position: Product Manager

Date Issued: April 29th, 2026

