

Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

Affected Part Numbers:

- R1812-010
- R1812-014
- R1812-020
- R1812-035
- R1812-050
- R1812-075
- R1812-110
- R1812-110-16
- R1812-125
- R1812-150
- R1812-160

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- R1812-010 is replaced by R1812-010-R
- R1812-014 is replaced by R1812-014-R
- R1812-020 is replaced by R1812-020-R
- R1812-035 is replaced by R1812-035-R
- R1812-050 is replaced by R1812-050-R
- R1812-075 is replaced by R1812-075-R
- R1812-110 is replaced by R1812-110-R
- R1812-110-16 is replaced by R1812-110-16-R
- R1812-125 is replaced by R1812-125-R
- R1812-150 is replaced by R1812-150-R
- R1812-160 is replaced by R1812-160-R

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny

Position: Product Manager

Date Issued: April 29th, 2026

Samuel Kenny