

Dear valued customer, please be advised that the part number(s) listed in the table below have undergone a change that may impact form, fit, function, or material. A detailed breakdown of this change is provided within this document.

**Affected Part Number(s):**

641, 642, 643 series
----------------------

**Detailed Description of Change:**

Previously, these part series was susceptible to body-deformation due to over-torquing of the nuts on the studs. To increase the torque rating, guide angles were added to the body of the circuit breakers. The torque-rating has now increased from 2.4Nm to 3.5Nm.

**Effective Note:** December 1st, 2025

- Please note that parts using the original specifications may still be provided as OptiFuse works off the stock that it has on hand.

If you have any questions regarding this change, please contact OptiFuse at [sales@optifuse.com](mailto:sales@optifuse.com) or reach out to your local sales rep for further details.

Issued by: Sebastian Castaneda

Role: Application Engineer

Signed: *Sebastian Castaneda*