

## Part EOL Notice:

Dear valued customer, OptiFuse regrets to inform you that the part(s) listed below have been phased out and will no longer be produced moving forward.

### Affected Part Numbers:

PMA-LS-AC1-Q2S  
PMA-LS-DC1-Q2S  
PMA-KB-07-Q1R-BK  
PMA-KB-07-Q1R-GO  
PMA-KB-07-Q1R-BL  
PMA-KB-07-Q1R-GN  
PMA-KB-07-Q1R-RD  
PMA-KS-03-Q2S

Once the remaining inventory located at OptiFuse warehouse is depleted, the above item(s) will no longer be available for purchase.

If you require a replacement for this part, OptiFuse recommends using the below part(s):

- PMA-KS-03-Q2S is replaced by PMA-KB-03-Q2S

If you have any questions regarding this, please contact your sales representative.

Printed Name: Samuel Kenny  
Position: Product Manager  
Date Issued: 01/01/2024