

F6T Series Label Marking Notice

Dear Valued Customer,

During a production run for the F6T series fuses, an error was identified on the product labels. The marking that should have read “300VDC” was incorrectly printed as “300VAC.”

Please note that this labeling error does not affect the form, fit, function, or performance of the product. The fuses continue to meet the 600VAC and 300VDC ratings specified in the Optifuse datasheet.

This issue has been corrected, and all future production runs will be marked accurately as “300VDC.” Optifuse is currently replacing labels on products marked “300VAC.” During this transition, some products may be supplied with an updated label applied over the original label as Optifuse works through existing inventory.

If you have any questions or require further assistance, please contact your local sales representative or email us at sales@optifuse.com.

Samuel Kenny
Product Manager
Date: 06/26/2026

Signed: *Samuel Kenny*