

Part Non-Conformance Notice:

Dear valued customer, please be advised that the part number(s) listed in the table below have undergone a change that may impact form, fit, function, or material. A detailed breakdown of this change is provided within this document.

Affected Part Number(s):

LPX-01 Series

Detailed Description of Change:

After additional testing on the product, the amperage rating of this part must be adjusted based on the wire sizes. If used with fuses rated higher than the updated ratings, these fuses will NOT serve as protection against overload currents and will only provide short circuit protection.

This updated rating has been determined through additional testing, and the product has not undergone any physical changes.

- 6AWG Wire Size: 60A Updated Rating
- 8AWG Wire Size: 50A Updated Rating

Effective Date: 05/04/2026

If you have any questions regarding this change, please contact OptiFuse at sales@optifuse.com or reach out to your local sales rep for further details.

Issued By: Samuel Kenny
Role: Product Manager

Signed: Samuel Kenny